



Tools & Material





Hex 2,5 mm




Screwdriver

A







B

28...30 full turns





C









E



F



*Wrap until it stops.
Then turn counterclockwise by 6 ... 8 full turns.*



The procedure for replacing the cam on the roll axis is the same as on the pitch axis.

H

